


# Dover Fire & Rescue Forestry 1



## Forestry 1 Facts

- Model Year 2000
  - 15 Years Old
  - 1 Ton Pickup
- Mileage – 33,244
- Carries 1,800 lbs. of water alone in the skid unit
- Used to Tow SAFE Trailer



# Forestry 1 Rust Issues

**Left, front side where plow attaches from outside looking through to inside of frame rail.**




**Left, front side where plow attaches from inside frame rail.**



**These frame rusted areas have already been repaired on the outside of the frame rails.**

# Forestry 1 Rust Issues

**Bottom edge of driver's side door.**



**Right, front side where plow attaches from inside frame rail.**



**These frame rusted areas have already been repaired on the outside of the frame rails.**